KDSP2 MANUAL ERRATA

February 4, 2004 (Rev A-2, for manual Rev A1)

PLEASE MAKE THE FOLLOWING IMPORTANT MANUAL CHANGES BEFORE YOU BEGIN ASSEMBLY. THESE CHANGES APPLY TO KDSP2 CTL FIRMWARE 3.10.

---

1. **Page 32 top of page:** With version 3.1 firmware, the FCS and EEP messages are no longer displayed.

2. **Two new features have been added to support K2 Main Firmware Version 2.04P or later.**

    If you have K2 main firmware version 2.04P or later, the Autonotch and Denoiser functions may now be toggled on and off directly from the front panel without using the DSP menu system.

    To toggle AUTONOTCH, simultaneously press and hold **AFIL** + **SPLIT**. The display will momentarily show:

nt on	or	nt oFF

    To toggle the DENOISER, simultaneously press and hold **AFIL** + **REC**. The display will momentarily show:

nr on	or	nr oFF

3. **Page 38 Error Messages:** Add "This message will also appear if the MCU firmware in the KDSP2 is prior to 3.10 and you attempt to use the **AFIL** + **SPLIT** or **AFIL** + **REC** shortcuts in K2 main firmware release 2.04P or later."