K2 A to B upgrade list

These upgrade kits may be ordered on-line at the Elecraft website.

BFOMDKT K2 BFO Toroid and PLL Ref Osc Xtal Upgrade

E850093 10M BPF, VFO/ALC Mod Kit for K2

Note: this may already be installed if the KPA100 has been installed, inspect to

be certain – If RF Board R10 is 470 ohms, it is present.

XFILMDKT Second Filter Upgrade

FWK2MCIO K2 MCU F/W Upgrade to 2.04; K2 IOC Upgrade to 1.09

E850089 Grill Cloth

Note: This is for the QRP top cover – KPA100 has grill cloth

E850138 K2 Temperature Compensated PLL Reference Oscillator

K2ATOBKT K2 basic A to B upgrade parts

Additional kits to be considered for an upgrade:

Examine the crystals on the RF Board and the KSB2 – if the crystals are marked 4915-S, they are the newer crystals and do not need to be replaced.

E850006 Set of 7 matched crystals for the CW K2

Note if KSB2 is present, the set of 14 (below) may be needed instead.

K2KSB2XTLS Set of 14 matched crystals for K2 RF board and KSB2

For KSB2 option upgrade:

Upgraded crystals as above – set of 7 for KSB2 only, set of 14 for K2 and KSB2.

KSB2MDKT PSK Upgrade for SSB option

Note: if KSB2 C38 is 47uF, this mod is already present.

SSBCAPKT KSB2 Wider Bandwidth Capacitor Kit

Note: this is optional, original bandwidth is 2.1kHz, current is 2.4kHz.

BFOMDKT must be installed to use the wider bandwidth.

KPA100 Upgrade:

Check the KPA100 for toroids with a blue core at RFC1 and L16 – if present, upgrade is not needed.

KPA100UPKT KPA100 upgrade kit – will upgrade all older KPA100s.

KPA100SHLDKT KPA100 shield upgrade.

Contains a speaker magnet shield and shield with grounding spring clips and has a narrow slot over the SO-239 ANT jack. It also has solder lugs to connect the

SO-239 to the outer surface of the shield plate.