Elecraft W2 Automatic Power On Modification

Revision A, December 15, 2009 Copyright © 2009, Elecraft, Inc. All Rights Reserved

Introduction

With this modification the W2 will turn on when 12VDC is applied without pressing the POWER button. The modification involves soldering a short wire jumper onto the main circuit board. Only the top cover need be removed to install the jumper.

Important Operating Notes for Modified Units


- 1. Pressing the POWER button will turn the unit off, but not on. If you press the POWER button, you must remove and reapply 12VDC to turn the unit on.
- 2. To prepare the W2 to download new firmware, hold the SENSOR button while applying 12VDC power. When you release the SENSOR button, the green 1 LED should blink, indicating the W2 is ready to receive new firmware.

Installing the Jumper

⚠ Observe ESD precautions when working inside your W2. Wear an ESD wrist strap or touch an unpainted, metal ground frequently while working. Use an ESD-safe soldering iron.

☐ Remove the W2 top cover. It is held in place by two flat head screws on top and two pan head screws on the back.

☐ Install the jumper as shown below. It is not necessary to put the jumper through the pads. Recommend you solder the jumper across the top of the pads as shown. Be sure you don't create a solder bridge to the end of R32.



Replace the top cover. Be sure you replace all four screws.

That completes the W2 Automatic Power On modification.