


K144XV REFERENCE OSCILLATOR PHASE LOCK OPTION MANUAL ERRATA

Rev. A2-2, December 5, 2015
E740155E

MAKE THESE CHANGES TO YOUR MANUAL BEFORE STARTING INVENTORY AND INSTALLATION

A new synthesizer pc board is now being shipped for your K3. The following changes are required if your K3 has the newer KSYN3A synthesizer board instead of the original KSYN3 board. The two boards are shown below:



Page 8: If your K3 has the new KSYN3A synthesizer, only one TMP coaxial cable is used as shown below. Do not connect a cable to the KREF3 board as shown in Figure 4 in the manual.

