

KAT2 ANTENNA TUNER MANUAL ERRATA

Rev F-1, March 14, 2016

PLEASE MAKE THE FOLLOWING CHANGES TO THE MANUAL

Page 2 (Parts List): Change the description of C55 from “ceramic trimmer” to “trimmer capacitor”.

KAT2 ANTENNA TUNER MANUAL ERRATA

Rev F-1, March 14, 2016

PLEASE MAKE THE FOLLOWING CHANGES TO THE MANUAL

Page 2 (Parts List): Change the description of C55 from “ceramic trimmer” to “trimmer capacitor”.