

KAT100 MANUAL ERRATA

Rev. D-2, August 31, 2016

**THESE MANUAL CORRECTIONS MUST BE MADE
BEFORE YOU BEGIN ASSEMBLY**

1. **Page 5 (Parts List), C31:** Change the part number from E540001 to E540012.
2. **Page 9, Right Column, Third Checkbox Step:** Change “ceramic trimmer capacitor” to just “trimmer capacitor”. The shape of the trimmer capacitor may not match the outline on the board. It may be installed in any orientation that fits the holes.