

KAT2 ANTENNA TUNER MANUAL ERRATA

Rev E-1, October 31, 2011

PLEASE MAKE THE FOLLOWING CHANGES TO THE MANUAL BEFORE PROCEEDING TO ENSURE THAT THE KAT2 FUNCTIONS CORRECTLY

Page 16, third assembly step: Add the following at the end of this step: "Make sure the shield wire in J7 is closest to the side of the K2 when J7 is plugged into P6 on the K2 RF Board."

KAT2 ANTENNA TUNER MANUAL ERRATA

Rev E-1, October 31, 2011

PLEASE MAKE THE FOLLOWING CHANGES TO THE MANUAL BEFORE PROCEEDING TO ENSURE THAT THE KAT2 FUNCTIONS CORRECTLY

Page 16, third assembly step: Add the following at the end of this step: "Make sure the shield wire in J7 is closest to the side of the K2 when J7 is plugged into P6 on the K2 RF Board."