

# K3 KIT ASSEMBLY MANUAL ERRATA

Rev. L3-2, December 22, 2010

<p><b>MAKE THESE CORRECTIONS TO YOUR MANUAL BEFORE YOU BEGIN ASSEMBLY.</b></p>
--

1. **Page 57, first step:** Delete “(Error! Reference source not found.)” and insert (Figure 83).
2. **Page 61, step under Fan Opening Cover:** Add to the step, “Install a BNC Hole Cover in the opening marked ANT 3 in the panel. This opening is provided for the 2-meter antenna BNC connector should you install the K144XV 2-meter option later.”
3. **Page A-6, Add to the description of the “Panel Blank, (KPA3 Fans)”:** The fan panel has a hole for a BNC connector marked ANT 3.
4. **Page A-10, E850263 K3 Miscellaneous Bag:** Change the quantity of “BNC Hole Cover” from 2 to 3.